


CORNER RECORD

Document Number 97-219

City of RIVERSIDE, County of RIVERSIDE, California

Brief Legal Description SELY. LINE LOT 4 M.B. 71/89.90. IN N.W. 1/4 SEC. 10, T. 35, R. 5 W. S.B. M.
(Include: Sec., Twp., Rge., and Meridian or Rancho)
W.D. 4632 OJEDA E.P.F.B. 124/21



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey 5/8/97

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE SKETCH ON REVERSE SIDE.


A description of the physical condition of the monument as found and as set or reset:

SEE SKETCH ON REVERSE SIDE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 15, 1997.


Signed Ernest Pintor L.S. or R.C.E. Number 3259
EXPIRATION DATE: 6/30/00



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 15 1997 and examined and filed May 24 1997.

Signed D. W. Beechcroft Title Senior L.S.



County Surveyor's Comment _____

THE FILING OF THIS CORNER RECORD
DOES NOT RELIEVE THE SURVEYOR
FROM ANY RESPONSIBILITY OF THE
FILING OF A RECORD OF SURVEY